



Part & Spare Parts

Accessories : Gear Air Motor Pump



Gast Air Motor

Model	Direction	Mounting Type	Max RPM	Output HP	Output KW	Max Air CFM	Consumption M ³ /H
1 AM	REW	FACE/HUB	10000	0.45	0.33	20.5	35.1
2 AM	CW	FOOT	3000	0.93	0.68	30.0	49.5
4 AM	REW	FOOT	3000	1.70	1.30	78.0	132.5
6 AM	REW	FOOT	3000	4.00	3.00	128.0	228
8 AM	REW	FOOT	2500	5.25	3.90	175.0	293
16 AM	REW	FOOT	2000	9.50	7.00	275.0	475

P.General Products : 234 Moo.5,Prakasa Road.,Prakasa,Muang,Samutprakarn 10280 Thailand.

Tel: (662) 728-5246-8 Fax: (662) 728-5249

E-mail: info@p-general.com